

ID PFH 22-1(11), CASCADE - WARM LAKE
Photo Log

Latitude and Longitude was determined from a handheld GPS unit, all location are approximate
Coordinates were recorded with geographic coordinate system World Geodetic System 1984 (WGS84)

Photo No.	Lat:	Lon:	UTC		Notes
			Date	Time	
img_0194	44.518979	-115.966091	4/4/2007	2:53:58 PM	Identified frost heave location
img_0195	44.526004	-115.949372	4/4/2007	2:57:23 PM	Identified frost heave location
img_0200	44.527848	-115.944882	4/4/2007	3:07:44 PM	Identified frost heave location
img_0203	44.528016	-115.944433	4/4/2007	3:10:11 PM	Transverse crack, road side spring
img_0205	44.532084	-115.936727	4/4/2007	3:17:49 PM	Damage culvert outlet
img_0206	44.53201	-115.936847	4/4/2007	3:18:06 PM	Identified frost heave location
img_0207	44.545031	-115.920508	4/4/2007	3:26:16 PM	Alligator cracking, pothole, identified frost heave location
img_0208	44.544249	-115.921026	4/4/2007	3:30:54 PM	Alligator cracking, pothole, identified frost heave location
img_0209	44.543779	-115.921437	4/4/2007	3:31:54 PM	Transverse crack, pothole, identified frost heave location
img_0214	44.545253	-115.920581	4/4/2007	3:45:28 PM	24" culvert inlet
img_0219	44.554262	-115.912422	4/4/2007	4:06:53 PM	24" culvert outlet, identified frost heave location
img_0221	44.569381	-115.898881	4/4/2007	4:16:55 PM	Deep Creek crossing
img_0222	44.568877	-115.899381	4/4/2007	4:22:58 PM	Identified frost heave location
img_0224	44.578244	-115.886545	4/4/2007	4:41:12 PM	24" culvert inlet, identified frost heave location
img_0226	44.577643	-115.887727	4/4/2007	4:43:30 PM	Identified frost heave location
img_0227	44.57781	-115.887543	4/4/2007	4:43:53 PM	Standing water in ditch, indentified frost heav location
img_0228	44.57793	-115.887225	4/4/2007	4:44:37 PM	Standing water in ditch, indentified frost heav location
img_0231	44.586622	-115.873412	4/4/2007	5:02:22 PM	Creek crossing, transverse crack
img_0237	44.59541	-115.855035	4/4/2007	5:47:41 PM	Identified frost heave location
img_0239	44.595852	-115.853984	4/4/2007	5:51:25 PM	Asphalt curb, identified frost heave location
img_0240	44.595757	-115.854013	4/4/2007	5:57:00 PM	Identified frost heave location
img_0242	44.62549	-115.798447	4/4/2007	6:18:47 PM	Identified frost heave location



img_0219



img_0221

img_0222





img_0224

img_0226



img_0227



img_0228



img_0231



img_0237



img_0239



img_0240



img_0242

